

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe, N.M.
Lease No. MM 916254
Unit _____

		10	
X			

SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED

NOV 7 1957

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	X
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 24, 19 57

Well No. Cov't. 13-10 is located 1980 ft. from N line and 660 ft. from E line of sec. 10
SW 10 25N 12W T4N
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Bisti San Juan New Mexico
 (Field) (County or Subdivision) (State or Territory)


The elevation of the derrick floor above sea level is 6178 ft. (Approx. Ground)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

(Spudded 10-23-57)

10-23-24-57 Ran and cemented 8-5/8" 24# J-55 casing at 103' with 100 sacks treated cement. Good returns. Flanged up and waited on cement. Tested BHP with 700 PSI 15 minutes, O.K.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil Company
 Address 101 South Behrend
Farmington, New Mexico

By B. W. Shepard
B. W. Shepard
 Title Exploitation Engineer