



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe, N.M.

Lease No. 33-10

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<u>Subsequent report of well completion</u>	<input checked="" type="checkbox"/>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 15, 1957

Well No. 33-10 is located 2110 ft. from N line and 1250 ft. from E line of sec. 10

33 10 (4 Sec. and Sec. No.) 25N 12W N.M.
(Twp.) (Range) (Meridian)
Bisti San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the Kelly Bushing above sea level is 5187.6 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

- 10-22-57 Cemented 4 1/2" 9.55 I-55 casing at 4885' with 150 sacks cement.
- 10-27-57 Perforated four 1/2" hole/ft. 4749-70, 4776-85, 4818-28, 4833-47.
- 10-28-57 Sand-oil fractured with 35,000 gal. crude oil, 1/2 gal. sand.
- 10-29-57 Formation broke down at 2100 psi.
- 10-30-57 Found sand fill at 4777' (108' from bottom) bailed.
- 10-30-57 Cleaned out to 4870'1. Landed tubing at top of perforations.
- 11-13-57 Swabbed well to flowing.
- Initial Production: Flowing 760 B/D (R) gross, 759 B/D (R) clean, 0.1% cut, 30/64" choke, 287 MCF/D gas, GOR 380, TP 180, CP 300. Completed 11-13-57

I understand that this plan of work must receive approval in writing by the Geological Survey before operation may be commenced.

Company Shell Oil Company
Address 101 South Behrend
Farmington, New Mexico

RECEIVED
NOV 22 1957
OIL CON. COM.
DIST. 2
By W. C. Miller
R. S. Mac Alister, Jr.
Title Division Exploitation Engineer