



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office San Juan, N.M.

Lease No. 811-11421

Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 20, 1958

Well No. 12-10 is located 2010 ft. from [N] line and 1931 ft. from [E] line of sec. 10

10 (1/4 Sec. and Sec. No.) 25N (Twp.) 12E (Range) 106W (Meridian)
1st (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the Well casing above sea level is 6232 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 11-7-58.

11-7-58

run and cemented (96%) 8-5/8", 24#, J-55 casing at 106' with 100 sacks, 120 cubic feet Portland cement treated with 2% calcium chloride (surface temperature 45°, formation temperature 75°, estimated strength of cement after 12 hours = 100 psi). Flanged up and waited on cement. Pressure tested casing and VOF with 900 psi, OK.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil Company

Address 705 Municipal Drive

Farmington, New Mexico

Original signed by
B. W. SHEPARD

By

Title Production Engineer