

Inspected 6-27-78 RTH OK CR

Form 9-331
(May 1963)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1421.

5. LEASE DESIGNATION AND SERIAL NO.
L. M. Phillips No. 7
NM 070322

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Water Injection Well	7. UNIT AGREEMENT NAME Carson Unit
2. NAME OF OPERATOR Shell Oil Company	8. FARM OR LEASE NAME Unit
3. ADDRESS OF OPERATOR 1700 Broadway, Denver, Colorado 80290	9. WELL NO. 32-10
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2010' FNL & 1931' FEL Section 10	10. FIELD AND POOL, OR WILDCAT Bisti
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6239' KB
	12. COUNTY OR PARISH San Juan
	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	
(Other) <input type="checkbox"/>		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

See attachment


APPROVED

WILL SEND FINAL SUNDRY WHEN LOCATION
CLEANED AND READY FOR INSPECTION

JUN 28 1978

R. J. McGRATH

DISTRICT ENGINEER



18. I hereby certify that the foregoing is true and correct

SIGNED <u>R. J. McGrath</u>	TITLE <u>Div. Opers. Engr.</u>	DATE <u>SEP 27 1977</u>
-----------------------------	--------------------------------	-------------------------

(This space for Federal or State office use)

APPROVED BY _____	TITLE _____	DATE _____
-------------------	-------------	------------

CONDITIONS OF APPROVAL, IF ANY:

cc: NMO&GCC

NEW MEXICO OIL CONSERVATION COMM.
1000 RIO BRAZOS RD.
ALBUQUERQUE, NEW MEXICO 87110
AZTEC See Instructions on Reverse Side

SEP 30 1977

PLUG & ABANDON				
SHELL OIL COMPANY	LEASE	CARSON UNIT	WELL NO.	BISTI 32-10
	DIVISION	WESTERN	ELEV	6239 KB
FROM: 9/15-19/77	COUNTY	SAN JUAN	STATE	NEW MEXICO

NEW MEXICO
BISTI FIELD

Carson Unit 32-10
(P&A)

"FR" TD 4935. PB 4850. AFE #570786 provides funds to plug & abandon well. 9/13 RU Bedford. Pulled on tbgs; pkr stuck. SEP 15 1977

Carson Unit 32-10
(P&A)

TD 4935. PB 4850. 9/14 Pkr stuck; could not unstick. Spt'd 25 sx cmt plug over Gallup perms thru tbgs already in hole. Turned tbgs to the right & backed off pkr @ safety jt. Pulled tbgs out of hole. SEP 16 1977

Carson Unit 32-10
(P&A)

SEP 19 1977

TD 4935. PB 4850. 9/15 Set jacks. Shot csg @ 1105 & spt'd 50 sx cmt plug across csg stub - Pictured Cliffs & Fruitland Coal. Pulled csg to 206 & spt'd 45 sx cmt plug across Ojo Alamo Sd & sfc csg stub. Pulled csg out of hole. Placed 10 sx cmt plug on sfc. Set abandonment marker & RD Bedford. FINAL REPORT