


(SUBMIT IN TRIPLICATE)

Land Office _____

Lease No. _____

Unit _____



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)


Well No. 33-11 is located 1240 ft. from N line and 1240 ft. from E line of sec. 11
11 (1/4 Sec. and Sec. No.) 25 (Twp.) 12 (Range) 12 (Meridian)
11 (Field) 12 (County or Subdivision) 12 (State or Territory)

The elevation of the derrick floor above sea level is 612 ft. (approx. ground)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Updated 9-12-58
 9-12-58 to 9-12-58 ran and cemented (27') 4-5/8" 262, 4-5/8" casing at 107' with 100 sacks cement treated with 20 gal. calcium chloride. Good returns to surface. Pressure test casing with 300 psi, OK.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil Company

Address 200 West Main Street

Marathon, Tex. 79401

By _____

Title _____