



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe, NM
Lease No. 21-9129
Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	<u>Subsequent Report of Re-completion</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 21-9 is located 600 ft. from N line and 1900 ft. from E line of sec. 9
9 (1/4 Sec. and Sec. No.) 25 (Twp.) 12 (Range) N 31 W (Meridian)
1st (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6150.4 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Status: TD 4930', FMSD 4851'
 5 5/8" casing at 236'
 5 1/2" casing at 4910'
 Perfs: 4753-4774'

Re-completion work:

5-1-58 sand-oil fractured with 50,000 gal crude oil and 1 1/2 gal. 20-40 mesh sand.
 5-3-58 cleaned out free sand from 4972-4980'. ran tubing to 4730'.
 6-21-58 Initial production: Flowing (2 1/3 hr. test) 639 b/d gross, 637 b/d oil rate,
 307 scf/d gas rate, 608 lb/d, 0.3% cut, 6 1/2" deep TP 150, completed 6-21-58

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil Company

Address 101 E. Behrend

Farmington, New Mexico

By B. W. SHEPARD
 Original signed by

Title B. W. Shepard
Exploitation Engineer