

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.  
L. M. Phillips No. 7  
NM 070322  
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Water Injection Well	7. UNIT AGREEMENT NAME Carson Unit
2. NAME OF OPERATOR Shell Oil Company	8. FARM OR LEASE NAME Unit
3. ADDRESS OF OPERATOR 1700 Broadway, Denver, Colorado 80290	9. WELL NO. 31-10
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL & 1980' FEL Section 10	10. FIELD AND POOL, OR WILDCAT Bisti
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 10-T25N-R12W
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6240' DF
	12. COUNTY OR PARISH San Juan
	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

See attachment

WILL SEND FINAL SUNDRY WHEN LOCATION  
CLEANED AND READY FOR INSPECTION



18. I hereby certify that the foregoing is true and correct

SIGNED L. Plautz TITLE Div. Opers. Engr. DATE SEP 27 1977

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

cc: NMO&GCC

\*See Instructions on Reverse Side

PLUG & ABANDON  
SHELL OIL COMPANY

FROM: 9/19-22/77

LEASE	CARSON UNIT	WELL NO.	BISTI
DIVISION	WESTERN	ELEV	31-10
COUNTY	SAN JUAN	STATE	6240 DF
			NEW MEXICO

NEW MEXICO  
BISTI FIELD

Carson Unit 31-10  
(P&A)

SEP 19 1977

"FR" TD 4995. PB 4933. AFE #529586 provides funds to plug & abandon well. 9/15 RU Bedford. Pulled on tbg; pkr stuck. 9/16 Worked on stuck pkr; could not get loose. Spt'd 20 sx cmt plug thru tbg in hole over & across Gallup perfs. Turned tbg to the right. Backed pkr off @ safety jt. Pulled tbg out of hole.

Carson Unit 31-10  
(P&A)

TD 4995. PB 4933. No report.

SEP 20 1977

Carson Unit 31-10  
(P&A)

TD 4995. PB 4933. No report.

SEP 21 1977

Carson Unit 31-10  
(P&A)

TD 4995. PB 4933. 9/17 Set jacks & worked csg. 9/19 Shot csg @ 1228 & spt'd 50 sx cmt plug over csg stub - Pictured Cliffs & Fruitland Coal. Pulled csg to 307 & spt'd 25 sx cmt plug over Ojo Alamo Sd & sfc csg stub. Pulled rest of csg out of hole. Placed 10 sx cmt plug on sfc. Set abandonment marker & RD Bedford.  
FINAL REPORT

SEP 22 1977