

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency Navajo Tribal
Allottee Ka-Da-Pah
Lease No. 14-20-403-2423

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Ka-Da-Pah

Farmington, New Mexico February 24, 1958

Well No. 2 is located 2000 ft. from S line and 1900 ft. from W line of sec. 3

SW/4 of Section 3
(1/4 Sec. and Sec. No.)

T-25-N
(Twp.)

R-12-W
(Range)

N.M.P.M.
(Meridian)

East-Lower Gallup
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 6501 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Ka-Da-Pah Well No. 2 was perforated with four shots per foot 4816-48, 4880-90, 4896-4910. Sand-oil fracked with 50,000 gallons oil and 50,000 pounds sand. Formation broke at 2650 pounds. Average injection rate 34 BPM. Injected 125 rubber balls during frac for selective treatment. A pumping unit has been installed on Ka-Da-Pah well no. 2 and well is still being tested to recover free oil.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Pan American Petroleum Corporation

Address Box 467

Farmington, New Mexico

ORIGINAL SIGNED BY
By D. I. SCOTT

Title Field Clerk

