



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 078155
Unit Gov't Marys

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	<u>Sandfree</u>	<u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 11, 1958

Well No. 3 is located 660 ft. from [N] line and 1900 ft. from [W] line of sec. 1

G. M. M. Section 1 25N 13W New Mexico P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Dist. Gallup San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation ~~of the derrick floor~~ above sea level is 6211 ft. G.L.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Rigged up Welox, set Baker GI Bridge Plug # 4892. Rigged up Dowell. Loaded hole and broke down formation w/80 BO @ 25 BPH and 1850 psi. Sandfracked w/30,000 lbs sand and 450 gals L-90 fluid loss additive in 30,000 gals lease crude. Flushed w/150 BO. Maximum treating pressure 1850 psi, minimum treating pressure, 1450 psi. Final flush pressure 1600 psi. Total load oil 917 BO. Stabbed and flowed all load oil in 44 hrs. Loaded hole and killed well w/140 BO. Cleaned out 2 ft. sand. Drilled out bridge plug @ 4892' and cleaned out to 4945' KB. Landed 2" KUE tubing @ 4923' KB. Ran rods & pump well on beam.

PRODUCTION BEFORE WORKOVER - 99 BO - 10 BW
PRODUCTION AFTER WORKOVER - 125 BO - No BW

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The British-American Oil Producing Company

Address Box 180

Denver 1, Colorado

By _____

Title District Superintendent