


Form 9-381a
(Feb. 1951)

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 0116706
Unit San Juan



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 26, 1963, 19__

Well No. 1 is located 640 ft. from N line and 640 ft. from E line of sec. 3

54 SW Sec. 1 25N 12W Range
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
First San Juan San Juan
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6361 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

12-10-62

Circulated 3 hours. Went in and plugged wells as follows:

5200-4990 - 250' plug

4000-3800 - 200' plug


1800-1690 - 190' plug

1490-1300 - 190' plug

265-205 - 60' plug

25 sack plug to surface.

Job completed 11:00 PM 12-10-62. Location has been cleaned up and dry hole marked has been erected.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The British-American Oil Producing Company

Address P. O. Drawer 330

Permington, New Mexico

By Ray R. Stone

Title Field Superintendent