

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Indian Agency .....  
Window Rock, Arizona  
De Texas Co.  
Allottee .....  
1-149-IND-9114  
Lease No. ....

	X	

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	X	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

RECEIVED  
MAR 22 1960  
U. S. GEOLOGICAL SURVEY  
FARMINGTON, NEW MEXICO

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 17, 1960

Well No. 1 is located 790 ft. from N line and 1350 ft. from EW line of sec. 9  
14 Sec. and Sec. No. 25N (Twp.) 3E (Range) 14.00 (Meridian)  
Bellevue T.C. (Field) San Juan (County or Subdivision) New Mexico (State or Territory)


The elevation of the derrick floor above sea level is 3495 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well plugged November 5, 1959-perforations squeezed with 25 sax:  
400 lb. pressure: 320 feet of cement left in bottom of pipe: filled  
with heavy mud to 150 feet from top: 10 sax cement in top of pipe:  
4" pipe marker welded to casing: bull plug welded to top of casing.

(NO LOSS RUN)



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company De Texas Co.

Address 1152 Hudson, N.M.

Bellevue T.C., N.M.

By C. E. Stewart  
C. E. Stewart

Title Agent

