

(SUBMIT IN TRIPLICATE)

Indian Agency _____
Window Rock, Arizona

The Texas Co.
 Allottee _____
1-149-IND-9111
 Lease No. _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

			X

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

RECEIVED

MAR 21 1960

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 17 1960

Well No. 12 is located 1750 ft. from N line and 790 ft. from E line of sec. 5
NE SE Sec. 5 25N 3W T. 25. N. 3. W.
 (¼ Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Ballard Co. San Juan New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 64.22 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Plugged November 4, 1959: 20 sack squeezed per formation with 200 feet of cement left in bottom of pipe: Heavy mud filled to 140 feet from surface: Filled with 10 sack of cement: 4" pipe marker welded to casing: All casing left in hole: Bull plug welded to top of casing.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Ted H. White
Address 142 Truman, N.E.
Albuquerque, New Mexico

By W. H. Stewart
Agent

