Quitzau

## (SUBMIT IN TRIPLICATE)

Land (	Office	<b></b> .	Sai	ila	re
•	NI.		MM	042	224
	NO.				

(1)				
(Orig.	Sad .	4		
TIME -	60.7		74.	A. Olive
Tiore -		٠-٠		

## **UNITED STATES**

EPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

SUBSEQUENT REPORT SUBSEQUENT REPORT SUBSEQUENT REPORT SUBSEQUENT REPORT SUBSEQUENT REPORT SUBSEQUENT REPORT SUPPLEMENTARY WEI	
BY CHECK MARK NATURE OF REPORT, NOTIC	CE, OR OTHER DATA)
	May 4th , 1956
316 ft. from $\binom{N}{6}$ line and 12	89 ft. from E line of sec. 3
(Twp.) (Range)	(Meridian)
(County or Subdivision)	New Mexico
(County or Subdivision)	
505/d A . W 503/d 2	(Chata as Mossitors)
	SUBSEQUENT REPOR SUBSEQUENT REPOR SUBSEQUENT REPOR SUBSEQUENT REPOR SUBSEQUENT REPOR SUBSEQUENT REPOR SUPPLEMENTARY WE SUBSEQUENT REPORT. NOTICE SUPPLEMENTARY WE SUBSEQUENT REPORT. NOTICE SUPPLEMENTARY WE SUBSEQUENT REPORT.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cement-ing points, and all other important proposed work)

TD 2766'. Flowing 301 MCF/day. Sand-oil treated from 2715' to 2766' with 17,635 gallons diesel 4-14-56 oil and 42,765# sand, flushed with 2,765 gallons diesel oil. Maximum treating pressure 2250#, final pressure 900#, injection rate 30 barrels per minute. After 10 hours flowing 6,890 MCF/day.

I understand that this plan of work must receive approval in writing by the Geological Survey Company BENSON-MONTIN Address 405 West Broadway Farmington, New Mexico Title Field Superintendent ...



to the second