

Elm Ridge Resources, Inc.  
Carson 14 #324R  
Sec. 14-T25N-R12W  
San Juan, New Mexico

SLOPE TESTS

DEPTH

105  
350  
699  
1166


HOLE DEVIATION

0  
1/4  
3/4  
3/4

30-045-31007

State of New Mexico)

) ss  
County of San Juan )



I, Trudy Grubelnik, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Trudy Grubelnik

Subscribed and sworn before me this 12<sup>th</sup> day of November, 2002.

