

Elm Ridge Resources, Inc.
Jake Papa #1
Sec. 32-T25N-R11W
San Juan, New Mexico

SLOPE TESTS

DEPTH

120
320
956
1348
1819
2450
3019
3520

HOLE DEVIATION

1/4
1/4
1/2
1/2
1-1/4
3/4
3/4
1

State of New Mexico)

) ss
County of San Juan)



I, Trudy Grubelnik, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Trudy Grubelnik

Subscribed and sworn before me this 31 day of October, 2002.

Frank L. Pope

Notary Public

My commission Expires Oct. 8th, 2002