



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe

Lease No. 080213

Unit Rincon Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	<u>Water Frac.</u>	<u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 9, 1963

Well No. 186 is located 840 ft. from ~~XXXX~~ line and 1570 ft. from ~~W~~ line of sec. 33

SE/4 Sec. 33  
(4 Sec. and Sec. No.)  
Largo Gallup  
Basin Dakota  
(Field)

27N  
(Twp.)

7W  
(Range)

N.M.P.M.  
(Meridian)

Rio Arriba  
(County or Subdivision)

New Mexico  
(State or Territory)

The elevation of the derrick floor above sea level is 6725 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 9-27-63 set bridge plug at 6846' and perf. Callup at 6792-6800' w/4 SPT, fraced w/37,850 gallons water, 40 gal. Mortlo, 40,000# 40/60 sand, flushed w/7040 gallons water. I.R. 39.6 BPM, Max. pr. 3850#, BDP 3200#, tr. pr. 2700-2850, 3200#. ISIP 1200#, 5 Min. SIP 700#, flowing back water, no gas.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 990

Farlington, New Mexico

By OR G NAL SIGNED E. S. OBERLY

Title Petroleum Engineer