



Garrey Carruthers  
Governor

STATE OF NEW MEXICO  
**ENERGY AND MINERALS DEPARTMENT**  
OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD  
AZTEC, NEW MEXICO 87410  
(505) 334-6178

September 18, 1989

Ms. Berenda Flaherty  
Meridian Oil Inc.  
P.O. Box 4289  
Farmington, NM 87499

**Re: San Juan 27-5 Unit #97, M-31-27N-5W**

Dear Berenda:

An enclosed copy of the regularly scheduled bradenhead test on the referenced well indicates a casing failure. In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to initiate immediate remedial activity.

Yours truly,

A handwritten signature in cursive script, appearing to read "Charles Gholson".

Charles Gholson  
Deputy Oil & Gas Inspector

CH/gb

BRADENHEAD TEST REPORT  
(Submit 2 copies to above address)Date of Test 8-2-89 Operator MERIDIAN OIL INC.Lease Name SAN JUAN 27-5 UNIT Well No. 97 Location U M Soc. 31 Twp. 27 Rge. 05Pressure (Shut-in or Flowing) Dwt Tubing 385 Intermediate 0 Casing 0 Bradenhead closed

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH.

TIME:	PRESSURES:	
	INTERMEDIATE	CASING
5 Min.		<u>175</u>
10 Min.		<u>65</u>
15 Min.		<u>0</u>
20 Min.		
25 Min.		
30 Min.		

	BRADENHEAD FLOWED:	INTERMEDIATE FLOWED:
Steady Flow	<u>✓</u>	
Surges		
Down to Nothing		
Nothing		
Gas	<u>✓</u>	
Gas & Water		
Water		

If Bradenhead flowed water check description below:

Clear \_\_\_\_\_  
Fresh \_\_\_\_\_  
Salty \_\_\_\_\_  
Sulfur \_\_\_\_\_  
Black \_\_\_\_\_Remarks: As bradenhead decreased  
in press so did casing  
(Packer Test 11/1)**RECEIVED**

AUG 28 1989

OIL CON. DIV

By R. A. McDaniel DIST. 3

LEASE OPERATOR

Position

Witness \_\_\_\_\_

CASING LEAK

AUG 25 1989