Dredon I	>	. 42-R358.4.
DRINKS!	Sureau No	. 43-KX59 A
A		
ADDIOVE	expires 19	2_21_AA

GPO 9 18 507

(Feb. 1961)					
			_		

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	87				
Lease No. 079493-A					
Unit San	June	27-5			
	e dere				

SUNDRY I	NOTICES AN	ND REPO	ORTS ON	WELLS	
NOTICE OF INTENTION TO DRILL	SHUT-OFF	SUBSEQUENT R SUBSEQUENT R SUBSEQUENT R SUBSEQUENT R	REPORT OF WATER REPORT OF SHOOTI REPORT OF ALTERI REPORT OF RE-DEFI REPORT OF AREA RY WELL HISTORY	ING OR NEIDIZING. NG CASING. LIGNG OR REPAIR 6 10	ST VED
(INDICATE	ABOVE BY CHECK MARK NA	TURE OF REPORT,	NOTICE, OR OTHER	DATA)	
Vell No. 27 (FM) is located	990 ft. from	S line and	690 ft. fro	$\mathbf{m} \begin{bmatrix} \mathbf{E} \mathbf{s} \\ \mathbf{W} \end{bmatrix} \text{ line of sec}$,
(1/4 Sec. and Sec. No.)	(Twp.) (Ra	nge)	(Meridian)	*****	
(Field)	Rio Arriba		Jen Jen	/ Mexico	
ate names of and expected depths to obj	ective sands; show sizes, w ing points, and all other	eights, and length important propos	s of proposed casi: ed work)	ngs; indicate mudding j	obs, cement
igud date 6-1-57. In 6-2-57 Total Depth 26 Ian 6 joints, 10 3/4', 3 Vegular coment circulate Ield 500# 30 mimutes.	2.754. SH Casi	af (845.) t	-n a 255	with 250 and	ke
			OIL COL	3 1957 N. com 17. 3	
I understand that this plan of work must mpany El Paso Satur	nt receive approval in writi	ng by the Geologic	cal Survey before o	perations may be comm	enced.
dress Sox 997					
Fernington, M	W Mexico	Ву	Original Sig	gned D. C. Johi	nston
	· 			m Engineer	