



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office San Juan
Lease No. 379367-A
Unit Pinson Hall

SUNDRY NOTICES AND REPORTS ON WELLS

| | |
|--|--|
| NOTICE OF INTENTION TO DRILL | SUBSEQUENT REPORT OF WATER SHUT-OFF |
| NOTICE OF INTENTION TO CHANGE PLANS | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | SUBSEQUENT REPORT OF ALTERING CASING |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL | SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | SUBSEQUENT REPORT OF ABANDONMENT |
| NOTICE OF INTENTION TO PULL OR ALTER CASING | SUPPLEMENTARY WELL HISTORY |
| NOTICE OF INTENTION TO ABANDON WELL | |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 17, 1960

Well No. 122 is located 170 ft. from S line and 72 ft. from E line of sec. 8

36 Sec. 26 215 4 S.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Co. Stanton P.M. Ala. Ariz. New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 524 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

4-11-60. Total depth 3361'.
Run 11 joints 3 1/2", 15.50#, 4-57 casing (3350') set at 3350' with 50 sacks regular cement, 50 sacks Pozmix, 25 Gal, 25/ Flocote, followed by 50 sacks regular cement.

Held 1000' for 30 minutes.

Top of cement by temperature survey at 3490'.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Paso Natural Gas Company

Address Box 777
Farmington, New Mexico

By Original Signed U. L. Johnson
Title Petroleum Engineer