



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Approval expires 12-31-60.

Land Office State of New Mexico
Lease No. 07934
Unit Elmore

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 10-27-92 is located 105 ft. from [N] line and 100 ft. from [E] line of sec. 3
27N 27E
 (Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Co. Blaine
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 1000 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

10-27-92, Total Depth 3204'.
 Ran 10 5/8" 15.5 lb, 5-55 casing (3195') set at 304' with 50 sacks
 regular cement, 50 sacks Formula, 4 1/2 Col, 1 1/2 Pileole, etc. followed by 50 sacks
 regular cement.
 Held 1000' for 30 minutes.
 2% of cement by temperature survey at 2245'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Elmore Natural Gas Company

Address Box 57
Arrington, New Mexico

Original Signed EWELL N. WALSH

By Petroleum Engineer
 Title