## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

			lls		
		<u> </u>	<del></del>	5.	Lease Number
					SF-079391
. Type of GAS	Well		e e e e e e	6.	If Indian, All. o Tribe Name
0.10				7	
Name of	Operator	· · · · · · · · · · · · · · · · · · ·	_	7.	Unit Agreement Na
BI 1E	RLINGTON				
	マスチナカアーナニビ	& GAS COMPANY			San Juan 27-5 Uni
				8.	Well Name & Numbe
Address	& Phone No. of Opera	ator	_		San Juan 27-5 U #
PO Box	4289, Farmington, N	M 87499 (505) 326-9700		9.	<b>API Well No.</b> 30-039-07113
Locatio	n of Well, Footage,	Sec., T, R, M	-	10.	Field and Pool
	, 1650'FEL, Sec.8, T-				Tapacito Pict. Cl
				11.	County and State
	Ō				Rio Arriba Co, NM
CHECK	APPROPRIATE BOX TO TH	NDICATE NATURE OF NOTIC	E. REPORT.	THER	DATA
	Submission	Type of A			
	Notice of Intent	Abandonment	Change o		
	_,	Recompletion	New Cons		
_X_	Subsequent Report	Plugging Back Casing Repair	Non-Rout	ine .	Fracturing ff
	Final Abandonment	Altering Casing			
	111141 1114114	X Other - Install			3
		pleted Operations blish circ. Circ hole c 25# coiled tbg, landed			458'. ТООН.
	- 3-00 MIRU. TIH, esta	blish circ. Circ hole c			458'. TOOH.
11-3	TIH w/1 4" 1.2	blish circ. Circ hole con 25# coiled tbg, landed	0 3453'. RD. DEC 200	0	te 12/11/00

NMOCU

than wo Joriu.