

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well  
GAS

2. Name of Operator  
Meridian Oil Inc.

3. Address & Phone No. of Operator  
PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M  
1650'FNL, 1850'FEL Sec.8, T-27-N, R-5-W, NMPM

5. Lease Number  
SF-079391

6. If Indian, All. or  
Tribe Name

7. Unit Agreement Name  
San Juan 27-5 Unit

8. Well Name & Number  
San Juan 27-5 U #70

9. API Well No.

10. Field and Pool  
Blanco MV/Basin Dk

11. County and State  
Rio Arriba Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input checked="" type="checkbox"/> Other - tbg & pkr repair	

13. Describe Proposed or Completed Operations

06-26-92 MOL&RU. Attempt to kill well w/2% KCl wtr. Killed MV, Dk still flowing. Attempt to run gge ring on Dk. Tbg down to 1.5, could not set thru donut. Attempt to blow donw, well died. ND WH. NU BOP. Tripping out w/tbg.

06-27-92 Work tbg, could not rotate. Ran free point, free to 5797'. Made chem.cut @ 5792'on 2 1/16" tbg. TOOH w/177 jts tbg. TIH, wash over pkr @ 5797'. TOOH. TIH w/overshot.

06-28-92 No go past 5760'. Fished free. TOOH. TIH, CO to 7846'. TOOH.

06-29-92 TIH, tag 10' fill. Blow clean. Ran pkr to 5672'. Hung up, pull out of rope socket. Fished, jarred free. TOOH, recovered setting tool, indicating pkr set.

06-30-92 TIH, sting into pkr @ 5800'. Try to PT, no hold. TOOH. TIH w/pkr plucker, wash over pkr. TOOH w/pkr. TIH w/scraper.

07-01-92 TIH to 7800'. Ran gge ring to 5900'. Set Mod D pkr @ 5871', could not shear off pkr, pull out of socket. Fish free. TOOH.

07-02-92 Ran 176 jts 1 1/4", 2.3#, JCW-50 IJ tbg landed @ 5739'. F Nipple @ 5733'. ND BOP. NU WH. Parted slickline, dropped tools. ND WH. NU BOP. Recovered tools. TIH w/1 1/4" as before.

07-03-92 Land 1 1/4" as before. ND BOP. NU WH. Released rig.

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Affairs Date 7/6/92

(This space for Federal or State Office use)

APPROVED BY \_\_\_\_\_ Title \_\_\_\_\_  
CONDITION OF APPROVAL, if any:

UNMOOD

FARMINGTON RESOURCE AREA  
BY [Signature]