State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division

S	Sundry Notices and I	Reports on Wel	lls	······································
		2	3003	ssigned by OCD) 92061700
1. Type of Well GAS		!	5. Leas	e Number
			5. Stat E-29	e Oil&Gas Lease #
2. Name of Operator		•		e Name/Unit Name
BURLINGTON RESOURCES				
RESOURCES OIL & GI	AS COMPANY			JUAN 27-5 UNIT
3. Address & Phone No. of Operator			152	
PO Box 4289, Farmington, NM 87	7499 (505) 326-9700	<i>(</i> -		Name or Wildcat
4. Location of Well, Footage, Sec., 1500' FNL, 1000' FWL, Sec. 16, 7		-	10. Elev	vation: 6564' GL
Type of Submission	Type of A			
		Change of		
Subsequent Report	Recompletion Plugging Back	New Const Non-Routi		uring
<u> </u>	Casing Repair	Water Shu	t off	_
Final Abandonment	Altering Casing K Other - Restimul		n to Inj	ection
13. Describe Proposed or Complete 1. MOL and pressure test cas 2. Acidize and foam fracture 3. Clean out well. 4. Return well to production	sing. e treat PC zone.	and the second of the second o		
		EGETT DEC 1 4 TE		
		77.00	rank#	
	((DIL COM. DISC 8	WIV.	
	New Con-	ga anglina nengir di shiriti ri		
SIGNATURE Jeggy Cale	Regulatory Adm	ninistratorI	December	8, 1999
(This space for State Use)				
OPIGINAL SIGNED BY CHAFILIE T. P				DEC 1 4 1999
Approved by	Title OFFITY OIL 8	R GAS INSPECTOR, I	λίι. 🗫 D	ate14 1999

SAN JUAN 27-5 UNIT #152

Section 16 E, T-27 -N R-05 -W Rio Arriba, New Mexico

Tapacito Pictured Cliffs Field Wellbore Schematic

