

Jenny A. Frost
District II
DEPUTY OIL & GAS INSPECTOR
District II
P.O. Drawer DD, Artesia, NM 88211
District II
1000 Rio Brazos Rd, Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

SUBMIT 1 COPY TO
APPROPRIATE
DISTRICT OFFICE
AND 1 COPY TO
SANTA FE OFFICE

(Revised 3/9/94)

Approved
PIT REMEDIATION AND CLOSURE REPORT

Operator: Conoco, Inc Telephone: 915-686-5453

Address: 10 Destra Drive, Suite 100W, Midland, TX 79705-4500

Facility Or: 28-7 # 196 Pit # 1
Well Name

Location: Unit or Qtr/Qtr Q Sec 10 T27N R7W County San Juan

Pit Type: Separator X Dehydrator Other

Land Type: BLM X State Fee Other

RECEIVED

OCT - 1 1997

OIL CON. DIV.
DIST. 3

Pit Location: Pit dimensions: length 8', width 5', depth 5'
(Attach diagram)

Reference: wellhead X, other

Footage from reference: 27'

Direction from reference: 35 Degrees X East North X
of
 West South

Depth To Ground Water:

(Vertical distance from
contaminants to seasonal
high water elevation of
ground water)

Less than 50 feet	(20 points)
50 feet to 99 feet	(10 points)
Greater than 100 feet	(0 points)
<u>10</u>	

Wellhead Protection Area:

(Less than 200 feet from a private
domestic water source, or; less than
1000 feet from all other water sources)

Yes	(20 points)
No	(0 points)
<u>0</u>	

Distance To Surface Water:

(Horizontal distance to perennial
lakes, ponds, rivers, streams, creeks,
irrigation canals and ditches)

Less than 200 feet	(20 points)
200 feet to 1000 feet	(10 points)
Greater than 1000 feet	(0 points)
<u>0</u>	

RANKING SCORE (TOTAL POINTS): 10