Form Approved. Budget Bureau No. 42-R1424

UNITED STATES DEPARTMENT OF THE INTERIOR

| UNITED STATES | 5. LEASE |
|--|--|
| DEPARTMENT OF THE INTERIOR | SF 078840 CAT S 545 |
| GEOLOGICAL SURVEY | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME |
| SUNDRY NOTICES AND REPORTS ON WELLS | 7. UNIT AGREEMENT NAME |
| (Do not use this form for proposals to drill or to deepen or plug back to a different | San Juan 28-7 Unit |
| reservoir. Use Form 9–331–C for such proposals.) | 8. FARM OR LEASE NAME |
| 1. oil gas X other | San Juan 28-7 Unit |
| | 9. WELL NO. |
| 2. NAME OF OPERATOR El Paso Natural Gas Company | 237 10. FIELD OR WILDCAT NAME |
| 3. ADDRESS OF OPERATOR | Basin Dakota |
| P.O. Box 289, Farmington, New Mexico 87401 | 11. SEC., T., R., M., OR BLK. AND SURVEY OR |
| 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 | AREA Sec. 19, T-27-N, R-7-W |
| below.) | <u>N.M.P.M.</u> |
| AT SURFACE: 1600'N, 1180'E | 12. COUNTY OR PARISH 13. STATE |
| AT TOP PROD. INTERVAL: AT TOTAL DEPTH: | Rio Arriba New Mexico |
| | 14. API NO. 3144 # 5544 |
| 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA | 15 FLEVATIONS (OLION OF ADD AND ADD |
| KEI ONLY ON OTHER BANK | 15. ELEVATIONS (SHOW DF, KDB, AND WD) 6665' GL |
| REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: | |
| TEST WATER SHUT-OFF [] | |
| FRACTURE TREAT \(\subseteq \) \(\subseteq \) SHOOT OR ACIDIZE \(\subseteq \) | 물을 보고 있는 사람들은 사람들이 되었다. |
| REPAIR WELL | (NOTE: Report results of multiple completion or zone |
| PULL OR ALTER CASING | change on Form 9–330.) |
| MULTIPLE COMPLETE CHANGE ZONES | |
| ABANDON* | |
| (other) | 그 그는 이 그 한빛원을 가운 원렸다. 중 사람 |
| 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state | e all pertinent details, and give pertinent dates |
| including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinen | irectionally drilled, give subsurface locations and |
| | |
| 10-22-78: TD 7641'. Ran 188 jts. 4 1/2", 10.59 at 7641'. Float collar set at 7625', stage tool | |
| stage w/338 cu. ft. cement, 2nd stage w/569 cu. | |
| cement. WOC 18 hours. Top of cement at 1700'. | The state of the s |
| | 그는 그는 그는 그를 다 바다 있는 것이 되었다. 이 사람들은 그 사람들은 사람들은 것이 되었다. |
| 5-19-79: PBTD 7625'. Tested casing to 4000#, | |
| 7467,7486,7495,7508,7514,7529,7549,7576,7582' w, | |
| 47,500# 10/20 sand, and 114,960 gal. gelled water | er. Flushed w/4914 gal. water. |
| | |
| | |
| | |
| | |
| Subsurface Safety Valve: Manu. and Type | Set @ |
| 10 I haraby Artifuttot the foresting is true and correct | |

(This space for Federal or State office use)

TITLE Drilling Clerk

DATE _ TITLE _

MAY 2 2 1979

U. S. CEOLOGICAL SURVEY DURANGO, COLO.

Tagge Journal of Section of Section County Section County Section of Section