## UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**


PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON\* (other)

Dec. 1973	Budget Bureau No. 42-R1424
UNITED STATES DEPARTMENT OF THE INTERIOR	<b>5.</b> LEASE SF 079364
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME Rincon Unit 8. FARM OR LEASE NAME
1. oil gas well other	Rincon Unit 9. WELL NO.
2. NAME OF OPERATOR  El Paso Natural Gas Company 3. ADDRESS OF OPERATOR Box 289, Farmington, New Mexico 87401	135A  10. FIELD OR WILDCAT NAME  S. Blanco PC & Blanco MV  11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 1840'N, 870'W AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	AREA Sec. 29, T-27-N, R-6-W  N.M.P.M.  12. COUNTY OR PARISH Rio Arriba N.M.  14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6664' G.L.
REQUEST FOR APPROVAL TO:  SUBSEQUENT REPORT OF:  TEST WATER SHUT-OFF  FRACTURE TREAT  SHOOT OR ACIDIZE  REPAIR WELL  PULL OR ALTER CASING	(NOTE: Report results of multiple completion or zone change on Form 9–330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

8-18-79: Spudded well. Drilled surface hole.

Ran 5 joints 9 5/8", 36#, K-55 surface casing 202' set at 216'. Cemented w/2248-19-79: cu. ft. cement. Circulated to surface. WOC 12 hours; held 600#/30 minutes.



AUG 2 9 1979

. EFC#10910#11 8Us