24.50 PA


Witness.

HINITED STATES

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE SF 080674 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME San Juan ::27-4 Unit 8. FARM OR LEASE NAME
1. oil gas other 2. NAME OF OPERATOR	San Juan 27-4 Unit 9. WELL NO. 138 (PM)
El Paso Natural Gas Company 3. ADDRESS OF OPERATOR P.O. Box 289, Farmington, NM	10. FIELD OR WILDCAT NAME Tapacito PC Ext. & Blanco MV 11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 1120'S, 1800'E AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	AREA Sec. 16, T-27-N, R-4-W NMPM 12. COUNTY OR PARISH 13. STATE Rio Arriba New Mexico 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinent	irectionally drilled give subsurface locations and
7-27-80: Spudded well. Drilled surface hole.Ran 5 josurface casing 229' set t 241'. Cemented wy to surface. WOC 12 hours; held 600#/30 minut	224 cu. ft. cement. Circ.
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct SIGNED	
(This space for Federal or State off	co uso)

AUG 05 1980

APPROVACGEPTED FOR RECORD CONDITIONS OF APPROVAL, IF ANY:



*See Instructions on Reverse Side



_ DATE _