5. LEASE

SF 080674

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

18. I hereby certify that the foregoing is true and correct

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

	=
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME San Juan 27-4 Unit
4 1	8. FARM OR LEASE NAME San Jun 27-4 Unit
1. oil gas vell definition of ther	9. WELL NO.
2. NAME OF OPERATOR	142
El Paso Natural Gas Company 3. ADDRESS OF OPERATOR	Blanco Mesa Verde
P.O. BOx 289, Farmington, New Mexico 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR
below.)	NMPM
AT SURFACE: 860'N, 850'E	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	Rio Arriba New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	7121' GL
REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES U. S. GEOLO	(NOTE: Report results of multiple completion or zone (Jonathange on Form 9-330.) GICAL SURVEY TON, N. M.
including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine 22-81: TD 4378'. Ran 118 joints of 7" 20& 23#, K-5 set at 4378'. Cmted w/ 280 cf. cmt. WOC 12 Top of cmt at*3200 '.	directionally drilled, give subsurface locations and nt to this work.)* 5 intermediate casing 4366'
Subsurface Safety Valve: Manu. and Type	NOV 2 - 1981 OIL CON. COM. DIST. 3

*See Instructions on Reverse Side

(This space for Federal or State office use)

Drilling Clerk

DATE

_ DATE .



October 23rd, 1981