Form 9–331 Dec. 1973 UNITED STATES	Form Approved. Budget Bureau No. 42–R1424
DEPARTMENT OF THE INTERIOR	<b>5. LEASE</b> SF 080675
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME San Juan 27-4 Unit
1 oil gas	8. FARM OR LEASE NAME San Juan 27-4 Unit
well well well other	9. WELL NO. 144
2. NAME OF OPERATOR El Paso Natural Gas Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR P.O. Box 289, Farmington, NM 87401	Blanco Mesa Verde  11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	AREA Sec. 4, T-27-N, R-4-W
AT SURFACE: 1520'S, 910'W AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	12. COUNTY OR PARISH 13. STATE Rio Arriba New Mexico
	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 7232' GL
ABANDON* U. S. GEOLO	lirectionally drilled, give subsurface locations and
7-81: TD 4444'. Ran 114 joints of 7", 20 & 23# H 4444!. Cemented w/ 281 cf. cement. WOC 1 cmt. @ 3000'.	K-55 intermediate casing 4432' sell hours; held 1200#/30 minutes.
)-81: TD 6696'. Ran 57 joints of 4 1/2", 10.5#, Float collar set at 6676'. Cemented w/ 4 <u>24</u>	K-55 casing liner 2406' set 4290 Lcf. cement. WOC 18 REFERENCE NOV 6 - 1981
Subcurface Safety Valves Many, and Type	OIL CON. COM. F
Subsurface Safety Valve: Manu. and Type	
18. I hereby certify that the foregoing is true and correct SIGNED SIGNED DANGE Drilling Cle	DIST. 3

DATE 1981

\_ TITLE \_\_