UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

casing

Spud- surface

PULL OR ALTER CASING MULTIPLE COMPLETE **CHANGE ZONES** ABANDON*

(other)

Form 9-331 Dec. 1973 UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	Form Approved. Budget Bureau No. 42-R1424 5. LEASE NM-0111-A 6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME		
1. oil gas well other 2. NAME OF OPERATOR	TURNER 9. WELL NO. #4		
CURTIS J. LITTLE 3. ADDRESS OF OPERATORP.O. Box 2487 Farmington, NM 87401	10. FIELD OR WILDCAT NAME So. Blanco P.C. 11. SEC., T., R., M., OR BLK. AND SURVEY OR		
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 790' FSL/790' FWL AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	Sec. 21-T26N-R7W 12. COUNTY OR PARISH 13. STATE Rio Arriba NM 14. API NO.		
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6918 G.L		
REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: D D D D D D D D D D D D D	MOTE: Report results of multiple completion or zone change on Form 9–330.)		

U. S. GLOLDGICAL SURVEY 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

4-21-83 SPUD well at 12:00 Noon. Drilled 8 3/4" hole to 122' G.L. Ran 3 joints of 7" K-55 23# casing measuring 122' ed @ 122' G.L.

Cemented surface pipe with 65 sx. Class "B" neat 6 = 1933 4-22-83: w/2% CaCl. Circulated 25 cubic feet of cementato. tessed. DIV. Plug down at 11:00 a.m. Pressure surface. DIST. 3 600 psi and held ok.

Subsurface Safety Valve: Manu. and			Set @	Ft.
18. I hereby certify that the foregoing	g is true and correct TITLE Agent	DATE	4-22-83	
	(This space for Federal or State	office use)		
APPROVED BY	TITLE	DATE _		

ACCEPTED FOR RECORD

*See Instructions on Reverse Side

MAY 0 1 1983



FARMINGTON DISTRICT