

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well ☐ gas ☒ well ☐ other

2. NAME OF OPERATOR

CURTIS J. LITTLE

3. ADDRESS OF OPERATOR

P.O. Box 2437, Farmington, NM 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

1810' FSL & 1560' FWL

AT SURFACE:

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☒

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) ☐

SUBSEQUENT REPORT OF:

☐

☐

☐

☐

☐

☐

☐

☐

☐

RECEIVED

AUG 25 1982

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

5. LEASE
SF-079107

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
TURNER

9. WELL NO.

#2

10. FIELD OR WILDCAT NAME

Otero Chacra/So. Blanco PC

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 25-T26N-R7W

12. COUNTY OR PARISH

RIO ARRIBA

13. STATE

NEW MEXICO

14. API NO.

30-039229942

15. ELEVATIONS (SHOW DF, KDB, AND WD)

6791' GL

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

8-12-82 Pressure tested casing to 2500 psi, held OK. Perf Chacra 3736-54 (GL) w/10 holes, 24 inches apart and 1 hole each @ 3836, 37, 40, 41 & 42. Ran 2 3/8" tubing (4.6#) w/Baker Retrievalmatic packer set @ 3597'. Acidized w/500 gals 7 1/2% HCl. BDP-2000 psi. Swabbed well dry. Ran three hour flow test, gauged 18.8 mcf/gd.

8-14-82 Pulled tubing and packer and fraced w/60,960 gals 70 quality foam, 56, 250# 20-40 sand. BDP-1350 psi, ATP-2600 psi. IR-20 BPM, ISIP-2500 psi.

8-19-82 Set Bridge Plug @ 2997', Pressure test to 3500 psi, Held OK. Perf Pictured Cliffs 2878-96 & 2908-26 (GL) w/10 holes per zone, 24 inches apart. Fraced w/65,573 gal 70 quality foam, 66,700# 10-20 sand.

Subsurface Safety Valve: Manu. and type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

Continued...

SIGNED Raymond Little TITLE: Agent

DATE August 25, 1982

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

ACCEPTED FOR RECORD

*See Instructions on Reverse Side

AUG 27 1982

NMOCC

BY SM

Attachment to Frm 9-331 SUNDRY NOTICES & REPORTS ON WELLS

Curtis J. Little
#2 Turner

.....continued

8-19-82 BDP-1500 psi, ATP-1650 psi, IR-20BPM, ISIP-1800 psi.