

N-24-27-2 /



P.O. Drawer 3337, 700 S. Tucker, Farmington, New Mexico 87499
(505) 327-4961 24-Hour Dispatch (505) 325-6892

December 12, 1994

Enre Corporation
P. O. Box 6027
San Antonio, TX 78209


Attn: Mr. Michelson

On the Jicarilla 24N #1 well at 6113' th
running directional surveys and did not recor
book.

SURVEYS-JICARILLA 24N #1

192' - 1°
414' - 3/4°
836' - 3/4°
1270' - 1/4°
1776' - 3/4°
2276' - 3/4°
2776' - 1°
3280' - 1-1/4°
3780' - 1-1/4°
4279' - 1°
4812' - 2°
4947' - 1-1/4°
5420' - 2°
6100' - 2-1/4°

201' - 1/4°
432' - 3/4°
932' - 3/4°
1431' - 1°
1931' - 1-1/4°
2430' - 1-1/4°
2879' - 1-1/4°
3403' - 1-1/2°
3848' - 1-3/4°
4308' - 1-1/2°
4746' - 1-1/2°
5118' - 1°
5596' - 1-1/2°
5826' - 1-1/2°
6299' - 1-1/4°


JOHN K. RICHARDSON
DRILLING SUPERINTENDENT

RECEIVED DEC 19 1994