Form 3.60-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135

Expires: March 31, 1993

5. Lease Designation and Serial No. SF-080385

SUNDRY NOTICES	AND	REPORTS	ON	WELLS	
----------------	-----	---------	----	-------	--

SUNDRY NOTICES AND Do not use this form for proposals to drill or t	6. If Indian. Allottee or Tribe Name	
Use "APPLICATION FOR PER	MIT—" for such proposals	7. If Unit or CA. Agreement Designation
SUBMIT IN T	RINCON UNIT	
1. Type of Weil		8. Well Name and No.
Oil X Gas Other		RINCON UNIT #178E
2. Name of Operator UNION OIL COMPANY OF CALIFORNIA		9. API Well No. 30-039-25434
3. Address and Telephone No.	(007) 00/ 15/2 First 11/	10. Field and Pool, or Exploratory Area
P.O. BOX 2620, Casper, WY 82602	(307) 234-1563 Ext. 116	Basin Dakota/Blanco
4. Location of Well (Footage, Sec., T., R., M., or Survey Description 1450' FSL & 1450' FEL Sec. 23, T27N-R7W	••	11. County or Parish, State Mesaver Rio Arriba, NM
	INDICATE NATURE OF NOTICE, REP	ORT, OR OTHER DATA
	TYPE OF ACTIO	
TYPE OF SUBMISSION		Change of Plans
X Notice of Intent	Abandonment Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
C: Suosequein respon	Casing Repair	Water Shut-Off Conversion to Injection
Final Abandonment Notice	Altering Casing Other WEEKLY REPORT	Dispose Water
13. Describe Proposed or Completed Operations (Clearly state all pertine)	<u>—</u> —	(Note: Report results of multiple completion on N
SEE ATTACHED WEEKLY REPORT	DESENVEN JUL 1985 ONL GONL POLIS DIEC. 8	
14. I hereby certify that the foregoing is true and correct	Tide Drilling Superintendent	Date 7-3-9 4
(This space for federal or State office use)		
	TitleACCE	PTED FOR RECORD
Conditions of approval, if any:		
Title :8 U.S.C. Section 1001, makes it a crime for any person knowing	giv and willfully to make to any department or agency of the Un	net Gales (10 fal 1995) thous or fraudulent state

RINCON UNIT #178E RIO ARRIBA CO., NM

WEEKLY SUMMARY

6-28-95

Finished TIH, Wash and ream 30' to bottom. Drilled to 5300. Repaired blower on light plant engine 2.5 hours. Now on bottom drlg.

Mixed and pumped 1-10bbl sweep

- 6-29-95 Drilled to 5747, Drop survey, Pooh. Hole in good shape on trip out.
- Service rig ,work blind & pipe rams, pu jars, tih in hole to 2200 tag bridge pu kelly, wash & ream 100'. Tih in hole to 5000', break circ. Tih to 5725 tag bridge, wash & ream 22'fill on btm. Drill 2' lost returns, pump premix tank, 400bbls.of 30ppb. magma-fiber, & 200bbls. from active system. No returns pull 12stds.Mix #2mud system & pump @40ppb.M-F 45vis.8.8ppg.+4ppb.calcium carbonate in premix. Pumped 750bbls. no returns, Mix #3 mud system 46vis. 45ppb. M-F,8.7ppg. Pumped approx. 200bbls. got returns@ 1840brs. returns approx.20%, all OJO water, pumped 550 more barrels 45ppb mud. Stopped pumps, cause out of fluid, fluid level @ bottom of BOPE,. Mix #4 mud system 42vis. 45ppbM-F 8.8ppg. pumped 100bbls. got returns 90% all water, pumped 75bbls more, vis.35 8.7ppg. turned to pit with 95% returns.circulated, ran 7 stds. in hole. Pu kelly broke circ.with 95% returns.Lost 2200bbls.

Mixed: 157sks. gel 564sks.Magma-Fiber 24sks.calcium carbonate

Comments:

- 7-1-95 Circulate and condtion mud, Drill for 18.5 hours 80/85rpm 10/12wob,avg.rop 31'hr.Lost approx. 750bbls. mud in last 24hrs.
 - Mixing mud in premix tank 35/40ppb M-F 40vis. 8.9ppg 8WL.Before adding to system.
- 7-2-95 Drill to 6383, lost returns pump premix tank, pull 8 stds. Pump 300bbls. have returns tih drill to 6394 lost returns pump premix + 350bbls. no returns pull 5 stds. mix Lcm have returns tih drill.

 Lost approx. 2300bbls last 24 Hrs.
- 7-3-95 Drilling with 85to95% returns, Drill from 6534 to 7193 in 23.5 hours, avg 28'/hr. Continue to mix Magma-Fiber to control losses.

 Lost approx. 2100bbls last 24hrs.