

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT--" for such proposals)

5. Lease

NM-03733

6. If Indian, Allottee or Tribe Name

7. Unit Agreement Name

1. Oil Well ☐ Gas Well ☐ Other ☐
GAS WELL

8. Well Name and No.

Breech 377

2. Name of Operator:

Caulkins Oil Company

9. API Well No.

30-337-25070

3. Address of Operator:

(505) 632-1544

P.O. Box 340, Bloomfield, NM 87413

10. Field and Pool, Exploratory Area

Dakota, Mesa Verde,
Chacra, Pictured Cliff

4. Location of Well (Footage, Sec., Twp., Rge.)

1165' F/S 1025' F/W Sec. 23, T-26-N, R-7-W

11. Country or Parish, State

Rio Arriba Co., New Mexico

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

☐ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☒ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

17. Describe Proposed or Completed Operations:

9-14-97 Spud 12 1/4" hole at 7:00 p.m.

9-15-97 TD 12 1/4" hole at 341'.

Ran new 9 5/8" 36# J-55 seamless casing to 321' G.L. and cemented with 150 sacks (180 cu. ft.) class "B" cement with 2% CaCl and 1/4# per sack cellophane flake, displaced with 24.6 bbls H2O, circulated 13 bbls cement to surface.

Plug down at 2:20 p.m.

Shut down for 12 hours. W.O.C.

9-16-97 Tested surface casing with 1500# for 30 minutes.

Held OK.

NOTE: The format is issued in lieu of U.S. BLM Form 3160-5

18. I HEREBY CERTIFY THE FOREGOING IS TRUE AND CORRECT

SIGNED:

Robert L. Verquer
ROBERT L. VERQUER

TITLE: Superintendent DATE: 09/16/97

APPROVED BY:

TITLE:

ACCEPTED DATE RECORD

CONDITIONS OF APPROVAL, IF ANY

SEP 23 1997