5. Lease UNITED STATES NMNM-03733 DEPARTMENT OF THE INTERIOR CEIVE: **BUREAU OF LAND MANAGEMENT** 6. If Indian, Allottee or Tribe Name SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different 113 reservoir. Use "APPLICATION FOR PERMIT--" for such proposals) 1. Oil Well [] Gas Well [] Other [] 8. Well Name and No **GAS WELL BREECH 377** 2. Name of Operator: 9. API Well No. Caulkins Oil Company 30-039-25690-00-C1 3. Address of Operator: (505) 632-1544 10. Field and Pool, Exploratory Area P.O. Box 340, Bloomfield, NM 87413 DAKOTA, GALLUP, MESA VERDE, CHACRA, PICTURED CLIFFS 4. Location of Well (Footage, Sec., Twp., Rge.) 11. Country or Parish, State 1165' F/S 1025' F/W Distr 3 SEC. 23-26N-7W Rio Arriba Co., New Mexico 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION [X] Notice of Intent [] Abandonment [] Change of Plans []Recompletion New Construction [] Subsequent Report [] Plugging Back [] Non-Routine Fracturing [] Casing Repair [] Water Shut-Off [] Final Abandonment Notice [] Altering Casing [] Conversion to Injection [X] Other Repair hole in tubing [] Dispose Water 17. Describe Proposed or Completed Operations: 3-25-99 This well is currently a dual Dakota - Gallup - Mesa Verde commingled below a packer and Pictured Cliffs -Chacra commingled above packer. Tests conducted indicate that a hole has developed in the Dakota - Gallup - Mesa Verde production string below the packer causing irregular plunger runs and reduced production. We intend to pull 1 1/4" Pictured Cliffs - Chacra tubing. T.O.H. with 2 1/16" Dakota - Gallup - Mesa Verde string with packer searching for holes in tubing. Replace any joints with holes or perforation marks with blast joints. Re-run 2 1/16" tubing with model R-3 packer, land tubing at approximately 7470' with packer set at approximately 3950'. Re-run 1 1/4" Pictured Cliffs Chacra production tubing to approximately 3900'. No new surface will be disturbed, location area will be cleaned up when workover operations are completed. Estimated starting date, April 20, 1999 NOTE: The format is issued in lieu of U.S. BLM Form 3160-5 18. I HEREBY CERTIFY THE FOREGOING IS TRUE AND CORRECT SIGNED:_ Robert TITLE: Superintendent DATE: March 25, 1999 Team Lead, Petroleum Management DATE: APR APPROVED BY:_ /S/ Duane W. Spencer CONDITIONS OF APPROVAL, IF ANY

MMOCD