

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 079156-A
Unit Gov't. Well

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		<u>Surface Gr.</u>	<u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 13, 1959

Well No. 2 is located 1980 ft. from N line and 1920 ft. from E line of sec. 24


C 18 S 26N 13W New Mexico P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Dist-Lower Gallup San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the ~~water level~~ ground level above sea level is 6235 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled 13 3/4" hole to 215' FB. Ran 5 joints, 200 ft., 9 5/8", 25.4 lb., Armo Spiral Weld Casing. Landed at 213' FB and cemented with 100 sx with 1/4 cu. ft. per sq. of Straterete and 100 sx of neat cement. Displaced cement to 168' FB with good returns to surface. Waited 24 hours and tested casing to 500 psi for 30 minutes. Held OK.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The British-American Oil Producing Company

Address P. O. Box 180

Denver-1, Colorado

Original Signed By:
Thomas M. Hogan

By

Title District Superintendent