

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Santa Fe**

Lease No. _____

Unit **Hickson**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	X
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 6, 1962

Well No. **3** is located **1850** ft. from **N** line and **1850** ft. from **W** line of sec. **35**

NW/4 Sec. 35
(1/4 Sec. and Sec. No.)

26N
(Twp.)

2W
(Range)

NMPM
(Meridian)

Ballard PC
(Field)

San Juan
(County or Subdivision)


New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is **7032** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Pulled 2-inch upset tubing and replaced with 2810 feet of 1-inch regular tubing with 3-foot perforated joint on bottom 8-26-1962. Manifolder well to produce through 1-inch tubing.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Magellan Company**

Address **P. O. Box 1741**

Farmington, New Mexico

By *Jack A. Chiles*
Title **Geologist**