

(SUBMIT IN TRIPLICATE)

Indian Agency Navajo

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee Navajo Tribal

Lease No. 14-22-043-070

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 11, 1961

Navajo Tract 27,
Well No. 1 is located 1900 ft. from N line and 660 ft. from E line of sec. 32


SE 1/4 Sec. 32 24N 19W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wilcox San Juan Utah
(Field) (County or Subdivision) (State or Territory)

The elevation of the ground above sea level is 5535 ft.
is elevation 546 ft.
DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

9- 1-61 Attempted DST No. 5 from 9555'-9582', Packer would not hold.

9- 9-61 DST No. 6, 9588'-10,000'. Tool open 30 minutes. Recovered 130' of drilling mud. Pressure: IN 4875, IF & FF & FCI 25, FH 4835. Bottom hole temperature 275°.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Pure Oil Company

Address P. O. Box 245
Hatch, Utah
Alpine 3-3811

By J. B. Strong
J. B. Strong
Title District Chief Clerk