## State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division

Sundry Notices and Reports on Wells	
	API # (assigned by OCD) 300450563000
1. Type of Well GAS	5. Lease Number
	6. State Oil&Gas Lease #
2. Name of Operator	E-5113-79 7. Lease Name/Unit Name
BURLINGTON	·
RESOURCES OIL & GAS COMPANY	WILSON A
2 Addison a Plana Way of Opensham	8. Well No. 1
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700	9. Pool Name or Wildcat BALLARD PICTURED CLIFFS
4. Location of Well, Footage, Sec., T, R, M	10. Elevation:
1296' FNL, 1298' FWL, Sec. 32, T-26N-N, R-08W-W, NMPM, San 3	Juan County
Type of Submission Type of Action	
X Notice of Intent Abandonment Change	
	nstruction utine Fracturing
Casing Repair Water S	Shut off
Final Abandonment Altering Casing Convers	
<u>X</u> Other - Tubing Installation	.1
1. MIRU. 2. TIH w/ 1 1/4" tubing and clean out to PBTD @ 2222'. 3. Land 1 1/4" tubing at 2108'. 4. RDMO. 5. Return well to production.	ECENTED NOV - 5 1889 D COM, DIV,
SIGNATURE Alfay (ale Regulatory Administrator (This space for State Use)	November 4, 1999
ORIGINAL SHOWED BY CHARGE T. PERSON	CTOR DIST AS NOV 5 1993

## Wilson A #1

## Section 32D, T-26-N, R-8-W San Juan County, NM

## BALLARD PICTURED CLIFFS WELLBORE SCHEMATIC

