

			X
	33		

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office **Santa Fe**  
Lease No. **078156**  
Unit **Gov. Salgo**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	<b>Set Production Casing</b> <b>X</b>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 28, 1957

Well No. **Salgo** **B-5** is located **660** ft. from **N** line and **660** ft. from **E** line of sec. **33**

**C-NE, NE Section 33** **26N** **13W** **New Mexico P.M.**  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
**Bisti-Gallup** **San Juan** **New Mexico**  
(Field) (County or Subdivision) (State or Territory)

The elevation of the **ground level** ~~surface~~ above sea level is **6228** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled to 5133' KB. Conditioned hole and ran 148 joints 5-1/2" OD, 14#, J-55 Sals. Casing, equipped with centralisers, scratchers and Baker Float Equipment. Casing landed at 5132' KB and cemented with 100 sac 3/4 Gal Cement. Displaced to 5064' KB under 1500 psi. Ran Temperature Survey, found top of cement at 4410' KB.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **The British-American Oil Producing Company**

Address **Box 180**

**Denver 1, Colorado**

Original Signed By:  
By **Thomas M. Hogan**

Title **District Superintendent**

1. The first part of the report is a general introduction to the project, which includes a brief history of the company and a description of the project's objectives.

2. The second part of the report is a detailed description of the project's methodology, which includes a discussion of the data sources and the statistical methods used to analyze the data.

3. The third part of the report is a discussion of the project's results, which includes a comparison of the results with the project's objectives and a discussion of the implications of the findings.

4. The fourth part of the report is a conclusion, which summarizes the project's findings and provides recommendations for future research.

5. The fifth part of the report is a list of references, which includes a list of the sources used in the project.

6. The sixth part of the report is an appendix, which includes a list of the data sources and a list of the statistical methods used in the project.

7. The seventh part of the report is a list of figures, which includes a list of the figures used in the project.

8. The eighth part of the report is a list of tables, which includes a list of the tables used in the project.