



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Santa Fe
Lease No. 078249
Unit Sullivan

SUNDRY NOTICES AND REPORTS ON WELLS

| | | |
|--|--|----------|
| NOTICE OF INTENTION TO DRILL | SUBSEQUENT REPORT OF WATER SHUT-OFF | |
| NOTICE OF INTENTION TO CHANGE PLANS | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING | |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | SUBSEQUENT REPORT OF ALTERING CASING | |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL | SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR | |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | SUBSEQUENT REPORT OF ABANDONMENT | |
| NOTICE OF INTENTION TO PULL OR ALTER CASING | SUPPLEMENTARY WELL HISTORY | |
| NOTICE OF INTENTION TO ABANDON WELL | <u>Sandoil Fracture</u> | <u>X</u> |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 10, 1956

Well No. 1-B is located 990 ft. from SW line and 990 ft. from W line of sec. 30SW Section 30
($\frac{1}{4}$ Sec. and Sec. No.)26N
(Twp.)12W
(Range)NMPM
(Meridian)Wildcat
(Field)San Juan
(County or Subdivision)New Mexico
(State or Territory)The elevation of the derrick floor above sea level is 6136 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

9-3-56 Total Depth 5033'. P.B.T.D. 4993'.

Sandoil fractured Lower Gallup perforated intervals 4943-4951 (6 shots/ft.) with 23,900 gallons oil and 30,000# sand. Breakdown pressure 3000#, maximum pressure 3000#, average treating pressure 2550#. Injection rate 39.2 bbls./min. Flush 7600 gallons. Natural gage none.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations are commenced.

Company El Paso Natural Gas CompanyAddress Box 997Farmington, New MexicoBy Ed Boyd
Title Petroleum Engineer