



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau 42-R358.3.
Approval expires 12-31-66.

Land Office Santa Fe
Lease No. H.M. 07352
Unit A. L. Duff

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	<u>Report of perforations</u>
	<u>Report of sand-trace</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 1 is located 660 ft. from S line and 1290 ft. from E line of sec. 19

SE 1/4 Section 19 (1/4 Sec. and 1/4 Sec. No.)
Wildcat (Field)
Santa Fe (County) Subdivision
New Mexico (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Perforated from 5304' to 5411' with 4 Schlumberger bullets per foot for total of 26 shots.

Sand-traced through perforations from 5304' to 5411' with 10,000 gal. of sand and 10,000 gal. crude oil. Flashed with 2,400 gal. oil. R.D. 4300' - Aug. 3600'. Min. 3000'. Injection rate 43 BPM. Time of treatment 17 min.



I understand that this plan of work must receive approval in writing by the Geological Survey before operation is commenced.

Company Shelly Oil Company

Address Box 426,
Farlington, New Mexico

By Wm. H. Duff

Title District Foreman

