



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe

Lease No. 97861

Unit \_\_\_\_\_

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

GEOLOGICAL SURVEY  
WASHINGTON, NEW MEXICO  
JUL 20 1959

Well No. 9 is located 1690 ft. from N line and 990 ft. from E line of sec. 22

22/4 (Sec. Co.) 200 (Twp.) 11N (Range) 10W (Meridian)  
Undesignated (Section) San Juan (Division) New Mexico (State or Territory)

The elevation of the ground level above sea level is 6056 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We wish to report running and cementing surface casing.

1. Drill 12 1/4" hole to 315'.
2. Run 239' of 9 5/8" OD 32.3# E-40 SMC casing with float collar set at 312'.
3. Cemented with 150 cc fog cement and circulated to surface 6/20/59.
4. WCT 24 hours. Pressure tested casing at 900 psi for 30 min. Pressure held OK 6/22/59.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Summit One Transmission Company

Address P. O. Box 1714

Burango, Colorado

By R. E. Walker

Title District Production Superintendent

