

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY El Paso Natural Gas Company, Box 997, Farmington, New Mexico
(Address)

LEASE Huerfano Unit WELL NO. 50 UNIT H S 22 T 26N R 9W

DATE WORK PERFORMED Jan. 29, 1956 POOL Ballard P.C.

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off

☐ Beginning Drilling Operations

☐ Remedial Work

☐ Plugging

☒ Other Water Fracture

Detailed account of work done, nature and quantity of materials used and results obtained.

Total Depth 2025'.

Water fractured Pictured Cliffs through interval 1965' - 2025'
with 34,620 gallons water and 55,000# sand. Breakdown pressure
1100#, maximum pressure 1450#, average treating pressure 1350#.
Injection rate 59.0 bbls./min. Flush 3400 gallons. Natural
gase 310 MCF/D.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____

Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____

Perf Interval (s) _____

Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

BEFORE

AFTER

Date of Test

Oil Production, bbls. per day

Gas Production, Mcf per day

Water Production, bbls. per day

Gas-Oil Ratio, cu. ft. per bbl.

Gas Well Potential, Mcf per day

Witnessed by _____

(Company)

OIL CONSERVATION COMMISSION

Name A. R. Kendrick

Title PETROLEUM ENGINEER DIST. NO. 3

Date FEB 28 1956

I hereby certify that the information given
above is true and complete to the best of
my knowledge.

Name E. S. O'Leary

Position Petroleum Engineer

Company El Paso Natural Gas Company



