(SUBMIT IN TRIPLICATE)

Land Office	SF

078899- A....

Unit

Western Pool Unit



## UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

## SUNDRY NOTICES AND REPORTS ON WELLS

SUBSEQUENT REPORT OF WATER SHUT-OFF	U. S. GEOLOGICAL SURVEY
SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	FARMINGTON, NEW MEXICO
SUBSEQUENT REPORT OF ALTERING CASING	FARINGIA
SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
SUBSEQUENT REPORT OF ABANDONMENT	
SUPPLEMENTARY WELL HISTORY	X
·	* 1
	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR SUBSEQUENT REPORT OF ABANDONMENT

June 7 , 19 61

 $\frac{N}{SX}$  line and 990 ft. from  $\frac{E}{XX}$  line of sec. 20 is located 99.) (t. from Well No. NE 1 NE/4 Sec 20 26N 11W 194 the Welling Nov. (Twj.) Rations (Merolisa) Basın Dakota San Juan New Mexico 1 period (County or Sub trasson)

The elevation of the derrick floor above sea level is 6191 ft.

## DETAILS OF WORK

State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cement-ing points, and all other important proposed work)

The following information was omitted from the USGS Log of Oil or Gas Well. Form 9-530

14.5/2 MCF/D CAOF =



Lunderstand	that this plan of work must receive approval in writing by the Geo	ological Survey before or	erations may be commenced.
Company	El Paso Natural Gas Products Company		
Address	Post Office Box 1560		

Farmington, New Mexico

ORIGINAL SIGNED BY: VAN E. DYKES

Petroleum Engineer

Title

Bv