

1	4	
0		

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY


Land Office Santa Fe
Lease No. SF 078431
Unit NW/4 Sec. 14
T-26N, R-8W, N.M.P.M.
San Juan, New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 15



Well No. 4 Nickson is located 490 ft. from S line and 1890 ft. from W line of sec. 14

SE/4, SW/4 Sec. 14
(1/4 Sec. and Sec. No.)

T-26N
(Twp.)

R-8W
(Range)

N.M.P.M.
(Meridian)

Pallard Pictured Cliffs
(Field)

San Juan County
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 6493 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

1- Ran 3 joints 97 feet of 9 5/8" 32.3#, H-40 casing. Landed at 80' G.L.
Cemented w/100 sacks regular cement. Cement circulated to surface.

2- Ran 60 joints 2435 feet of 5 1/2", J-55, 15.5# casing on September 28, 1957.
Landed at 2430 feet R.K.B. Cemented w/100 sacks regular cement w/2% gel.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Southern Union Gas Company

Address 1001 Burt Building

Dallas, Texas

By James J. Lohr

Title Drilling Superintendent