

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Santa Fe**
Lease No. **0806364**
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 19, 19 **59**

Well No. **1 Federal** is located **615** ft. from **N** line and **255** ft. from **E** line of sec. **18**
SW/4 **18** **26N** **13W** **107N**
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Dist **San Juan** **N. M.**
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **6486** ft.


DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Test was spudded 7-17-59.

200' of 8-5/8" - 26# casing was set and cemented with 150 sacks.

Before drilling the plug 1000# pressure was applied for 30 minutes with no drop.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **A. I. Middle Trust**

Address **Box 1507**

Salt Lake City, Utah

By _____

Title **Trustee**