

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS
(Submit to appropriate District Office as per Commission Rule 1106)

Company SOUTHERN UNION GAS COMPANY, 1700 Patterson St., Dallas 1, Texas
(Address)
Lease Ruthton Well No. 1 Unit N S 16 T 26N R 34
Date work performed 9-13-55 to 10-13-55 POOL BALLAD PICTURED CLIFFS

This is a Report of (Check appropriate block) ☐ Result of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☐ Plugging ☒ Other Work completed


Detailed account of work done, nature and quantity of materials used and results obtained.

- 1. Well was spudded on 9-13-55. Cemented 95' of 9 5/8" 36# surface casing with 80 sacks of cement on 9-15-55. Drilled plug and tested with 500# pressure with no leaks on 9-18-55.
- 2. Cemented 217 1/2' of 5 1/2" 15.5# casing with 100 sacks of cement on 9-21-55.
- 3. Well was hydrofractured from 217 1/2' to 2265' with 23,100 gallons of water and 20,000# sand on 10-8-55.
- 4. Run 2205' of 1" tubing on 10-13-55.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY
Original Well Data:
DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl. Date _____
Tbng. Dia. _____ Tbng. Depth _____ Oil String Dia _____ Oil String Depth _____
Perf. Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:	BEFORE	AFTER
Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____
Witnessed by _____		

Oil Conservation Commission
Name Emory C. Hunt Title Oil & Gas Inspector Dist. #3. Date NOV 9 1955
I hereby certify that the information given above is true and complete to the best of my knowledge.
Name H. C. Montgomery Position Drilling Superintendent Company SOUTHERN UNION GAS COMPANY



1. CONSTITUTIONAL COMMISSION	
2. NAME OF THE PARTY	
3. CHAIRMAN	3
4. VICE CHAIRMAN	
5. SECRETARY	1
6. TREASURER	
7. MEMBER	1 ✓
8. MEMBER	
9. MEMBER	
10. MEMBER	
11. MEMBER	
12. MEMBER	
13. MEMBER	
14. MEMBER	
15. MEMBER	
16. MEMBER	
17. MEMBER	
18. MEMBER	
19. MEMBER	
20. MEMBER	
21. MEMBER	
22. MEMBER	
23. MEMBER	
24. MEMBER	
25. MEMBER	
26. MEMBER	
27. MEMBER	
28. MEMBER	
29. MEMBER	
30. MEMBER	
31. MEMBER	
32. MEMBER	
33. MEMBER	
34. MEMBER	
35. MEMBER	
36. MEMBER	
37. MEMBER	
38. MEMBER	
39. MEMBER	
40. MEMBER	
41. MEMBER	
42. MEMBER	
43. MEMBER	
44. MEMBER	
45. MEMBER	
46. MEMBER	
47. MEMBER	
48. MEMBER	
49. MEMBER	
50. MEMBER	
51. MEMBER	
52. MEMBER	
53. MEMBER	
54. MEMBER	
55. MEMBER	
56. MEMBER	
57. MEMBER	
58. MEMBER	
59. MEMBER	
60. MEMBER	
61. MEMBER	
62. MEMBER	
63. MEMBER	
64. MEMBER	
65. MEMBER	
66. MEMBER	
67. MEMBER	
68. MEMBER	
69. MEMBER	
70. MEMBER	
71. MEMBER	
72. MEMBER	
73. MEMBER	
74. MEMBER	
75. MEMBER	
76. MEMBER	
77. MEMBER	
78. MEMBER	
79. MEMBER	
80. MEMBER	
81. MEMBER	
82. MEMBER	
83. MEMBER	
84. MEMBER	
85. MEMBER	
86. MEMBER	
87. MEMBER	
88. MEMBER	
89. MEMBER	
90. MEMBER	
91. MEMBER	
92. MEMBER	
93. MEMBER	
94. MEMBER	
95. MEMBER	
96. MEMBER	
97. MEMBER	
98. MEMBER	
99. MEMBER	
100. MEMBER	