

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. SP 076953
Unit J. W. Goddard

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	RECEIVED	SUBSEQUENT REPORT OF WATER SHUT-OFF	<u>Surface</u>	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	JUN 16 1958	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING		
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	U.S. GEOLOGICAL SURVEY	SUBSEQUENT REPORT OF ALTERING CASING		
NOTICE OF INTENTION TO RE-DRILL OR REPAIR	FARMINGTON, NEW MEXICO	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR		
NOTICE OF INTENTION TO SHOOT		SUBSEQUENT REPORT OF ABANDONMENT		
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY		
NOTICE OF INTENTION TO ABANDON WELL				

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 12, 1958

J. W. Goddard
Well No. 5 is located 1980 ft. from [S] line and 1960 ft. from [W] line of sec. 2

NE 1/4 - Sec. 2 26E 12N P.M.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Undesignated (Gallup) San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)


The elevation of the derrick floor above sea level is 5891 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

SPUNDED: 9:00 P.M., 5/30/58

Run & set 10-3/4" casing at 433' & cemented with 320 sks. reg. cement 25 CaCl.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Skelly Oil Company

Address Box 426
Farmington, New Mexico

By (Signature) J. W. Goddard

Title District Superintendent