


(SUBMIT IN TRIPLICATE)

Land Office Santa Fe, N.M.

Lease No. SF 078641AA

Unit _____



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<input checked="" type="checkbox"/>		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

_____ 1.6.60 _____, 19____

Well No. 2-B is located 762 ft. from {N} line and 889 ft. from {E} line of sec. 3

NE 1/4 sec 3 26N 11E _____
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

(Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We intend to plug this well as follows:
10 ex Cement 775' - 738'
5 ex. " 60' - 45'
a surface plug & clean up
3" pipe for marker



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Calto Oil Company

Address Dallas, Texas

Box 12266

By _____

Title agent

